

ORICO 3549RUS3_3559RUS3_固件分位更新固件分位更新 (专用固件，其他机型不适用！)
ORICO 3549RUS3_3559RUS3_Firmware Update (Special firmware, other models do not apply)


更新内容：

1. 解决了USB连接路由器设备不能同时读取多个硬盘的问题；
1.Solves the problem that the USB connecting router device cannot read multiple hard drives at the same time;
2. 解决了USB连接高清播放机/网络机顶盒设备不能同时读取多个硬盘的问题；
2.Solves the problem that the USB connection HD player/network set-top box device can't read multiple hard drives at the same time;


更新步骤：

Update steps:

1. 打开“Tool”，运行“JMMassProd2_v1_16_14_25.exe”.
- a. Open the "Tool", run the program "JMMassProd2_v1_16_14_25.exe".



2. 勾选“RD Version”，输入口令“jmicron”.
- b. Select "RD Version", enter the password "jmicron".



2. 勾选 "Firmware Update " 然后点击“Load F/W File” 加载“FW”文件
"JMS567_For_ORICO 3549RUS3_3559RUS3_v125.03.00.01.bin".
- c. Select "Firmware Update" and click "Load F / W File" to load "FW" file
"JMS567_For_ORICO 3549RUS3_3559RUS3_v125.03.00.01.bin".

